

## Camshaft Carrier Alignment Pins - for Stellantis Group DV4, DV5 & DV6 Diesel

The DV5 (1.5 BlueHDi) diesel engine in Toyota vehicles has a recall due to premature camshaft chain wear. Replacing the chain and sprockets requires removing and realigning the camshaft carrier, which is made easy with the Laser Tools 9396 alignment pins that ensure precise and hassle-free installation.



### Additional Information

- Applications include: Citroën, DS, Fiat, Vauxhall/Opel, Peugeot, Toyota DV4, DV5 & DV6 range of diesel engines (2005 - 2024).
- Designed to be used to align the camshaft housing on reassembly.
- Equivalent to OEM 0194-N, 2.000.022.900 & EN-52146.
- NOTE: Use in accordance with OEM instructions.
- Use with Laser Tools engine timing kit, Part No. 8311.

<http://lasertools.co.uk/product/9396>